
## Acrylic Projection Mount w/Sleeve INSTALLATION INSTRUCTIONS\*




Minimum recommended screw size is #6; maximum #10.


\*Mounting screws and anchors are not provided.




Use a level to place the sleeve (A) into its intended location and mark the mounting hole locations.




Using the marks from step 1, drill and install appropriate screw anchors for the application. (not included)




Fasten an end cap (C) to the sleeve (A) using the provided #4 screws (D).



Secure sleeve to wall using the appropriate fasteners for the application.





Slide in the bracket (B), then secure an end cap (C) to the sleeve (A) using the provided #4 screws (D).




**Notice:** If there is not enough clearance to the ceiling, simply rotate the sleeve (to where the previously fastened cap is on the top) and work upward.

## **INCLUDED HARDWARE:**









For more product information, installation tips, and quality signage merchandise, go to